

Inspection Photos

API: 05-067-07003

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602402

Inspection Date: 1/4/2018



Photo 1. View of the project area from the northwestern corner facing center. Stormwater run-on is occurring here and needs to be monitored.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 3. View of the western portion of the project area from northwestern corner facing southward. Revegetation is progressing with smooth brome (*Bromus inermis*), dropseed (*Sporobolus* sp.).



Photo 4. View of jointed goatgrass (*Aegilops cylindrica*) within the southern portion of the project area.