

Interim Reclamation and Stormwater Inspection

January 9, 2018

Operator: MALLARD EXPLORATION LLC - #10670

Location ID: 447898

Weld County, CO

SESW Section 31 T9N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Anderson Facility
Location ID: 447898



Photo 1. Photo taken from the southeast location, facing East. A sediment trap with a stabilized outlet has been installed. Operator may want to consider an additional sediment trap as this is the only sediment trap for a total disturbance of 19.17 acres which will not be reclaimed to reduce the total disturbance for interim reclamation.



Photo 2. Photo taken from the western location, facing South. A ditch BMP has been installed along the perimeter location.

Inspection Photos
Location Name: Anderson Facility
Location ID: 447898



Photo 3. Photo taken from the southern location, facing East. See comments under Photo 2.



Photo 4. Photo taken from the southern location, facing East. Vehicle tracking device installed. Culvert installed in conjunction with the ditch BMP.

Inspection Photos
Location Name: Anderson Facility
Location ID: 447898



Photo 5. Photo taken from the eastern location, facing North toward the topsoil stockpile. Straw mulch is blowing off topsoil which may need maintenance.



Photo 6. Photo taken from the eastern location, facing North. See comments under Photo 5.

Inspection Photos
Location Name: Anderson Facility
Location ID: 447898



Photo 7. Photo taken from the northeast location, facing South towards the topsoil stockpile. Photo illustrates portions of the topsoil are bare and may require additional stabilization.



Photo 8. Photo taken from the northern location, facing West. See comments under Photo 2.