

# Inspection Photos

API: 05-067-09471

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602409

Inspection Date: 1/4/2018



**Photo 1. View of the project area from the northeastern corner facing center.**





**Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing with crested wheatgrass (*Agropyron cristatum*) and blue grama (*Bouteloua gracilis*).**





**Photo 3. View of the southern portion of the interim reclamation area from the southeastern edge facing westward.**





**Photo 4. View of area in the southern portion of the project are with sparse revegetation. Vegetation in this area is largely annual weeds. This needs to be evaluated during the 2018 growing season and re-seeded by November 1, 2018 if desirable cover is not established.**





**Photo 5. View of erosional channels in the southern portion of the project area.**





**Photo 6. View of cobble run-down in the southern portion of the project area.**





**Photo 7. View of musk thistles (*Carduus nutans*) in the southern portion of the project area.**