

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2018

Submitted Date:

01/15/2018

Document Number:

688301005**FIELD INSPECTION FORM**Loc ID 439225 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: 600 N DAIRY ASHFORD RDCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
ConocoPhillips		COPColoradoReg@conocophillips.com	
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	Regulatory Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439224	WELL	DG	09/01/2017	LO	005-07231	Tiberius 4-64 8-7 4CH	WO

General Comment:[Bradenhead Test Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-595-8258

Corrective Action: _____ Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	Production tanks being installed.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	439224	Type:	WELL	API Number:	005-07231	Status:	DG	Insp. Status:	WO
BradenHead									
Comment:	<div>1/10/2018 Bradenhead Test, Form 42 #401506544 Casing 9 psi, Bradenhead -22" Hg took 1 min 30 secs to blowdown 0 min, Casing 9 psi, Bradenhead 0 psi 5 min, Casing 9 psi, Bradenhead 0 psi 10 min, Casing 9 psi, Bradenhead 0 psi 15 min, Casing 9 psi, Bradenhead 0 psi Operator will submit Form 17 electronically.</div>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Self Inspection	Pass	
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688301015	ConocoPhillips Tiberius 4-64 8-7 4CH Bradenhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4350527
688301016	ConocoPhillips Tiberius Form 17 1/10/2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4350528