

Inspection Photos
Location Name: [Champlin 485 Amoco #1]
API: 05-001-07900



Berms will not hold capacity of water tank



Need Cap on load line