

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2018

Submitted Date:

01/09/2018

Document Number:

688600213**FIELD INSPECTION FORM**

Loc ID 428669 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 1Name of Operator: UNKNOWN

Address: \_\_\_\_\_

City: \_\_\_\_\_ State: \_\_\_\_\_ Zip: \_\_\_\_\_

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425793	WELL	TA	10/12/2011	LO	077-40017	Lloyd and Lowell 1	TA

**General Comment:**

Orphan well plugging project. Contractor is RACS.

**Inspected Facilities**

Facility ID: 425793    Type: WELL    API Number: 077-40017    Status: TA    Insp. Status: TA

**Workover**

Comment: Remobilized.  
 Ran camera to 30', no visibility. Ran sinker bar, tagged at 372'.  
 Filled water tank.  
 Rigged up picked up BHA and power swivel. Off location 2:30.

Corrective Action: **Plug and abandon.**

Date: 01/16/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401508206	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4345134">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4345134</a>