

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2018

Submitted Date:

01/10/2018

Document Number:

689500482

FIELD INSPECTION FORM

Loc ID 316444 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		regulatory@foundationenergy.com	Regulatory
,		dnr_cogccengineering@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	
Allred, Josh	970-629-5914	jallred@foundationenergy.com	Rangely area

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274921	WELL	SI	05/01/2016	GW	103-10539	COLUMBINE SP FED 14C-13-4-104	TA

General Comment:

On location to conduct routine inspection

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Located at entrance of location – Missing nearest access road field wide.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	03/11/2018
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	866-767-3600	Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	CBM rotary pump		
Corrective Action:		Date:	
Type:	#		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 274921 Type: WELL API Number: 103-10539 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA - no leaks/venting. No current MIT on record or delinquent as required by Rule 326
Production records indicate well last produced in December 2011

Corrective Action: Well must have a successful mechanical integrity test performed or plugged as directed
by Rule 319 b (3) Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 01/20/2018

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass					
Ditches	Pass					

Comment: No sediment flow evident

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown

Lined: YES

Pit ID:

Lat:

Long:

Reference Point: SE

Other: _____

Length: 8

Width: 8

Lining:

Liner Type: Other

Liner Condition: Adequate

Comment: fiberglass

Corrective Action

Date: g

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401510042	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4346807
689500483	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4346796