

Inspection Photos

01/17/2018

Operator: MAGPIE OPERATING, INC - 52530

Location ID: 401718

Inspection Doc. Number: 682503090

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 401718



Photo 1: Photo taken from the north end of the former pit and facilities location, facing south. Photo shows large areas of the location remain predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per corrective actions.



Photo 2: Photo taken from the north end of the former pit and facilities location, facing southwest. Photo shows large areas of the location remain predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per corrective actions.

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 401718



Photo 3: Photo taken from the east end of the former pit/facilities location. Photo shows large areas of the location remain predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per corrective actions. 6 foot measuring stick for reference.



Photo 4: Photo taken from the southeast end of the former pit/facilities location. Photo shows large areas of the location remain predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per corrective actions.

Inspection Photos

Operator: MAGPIE OPERATING, INC - 52530

Location ID: 401718



Photo 5: Photo taken from the southeast end of the former pit/facilities location, facing west. Photo shows large areas of the location remain predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per corrective actions.



Photo 6: Photo taken from the west end of the former pit/facilities location, facing east. Photo shows large areas of the location remain predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per corrective actions.

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 401718



Photo 7: Previous inspection documented debris remaining on the location. Photo shows debris identified in previous inspection has not been removed. Debris appears to be a partially buried barrel.



Photo 8: Photo taken from the southwest end of the former pit and facilities location, facing north. Photo shows large areas of the location remain predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per corrective actions.

Inspection Photos

Operator: MAGPIE OPERATING, INC - 52530

Location ID: 401718



Photo 9: Photo taken from the west end of the former pit and facilities location, facing east. Photo shows large areas of the location remain predominantly bare and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per corrective actions.



Photo 10: Photo taken from the adjacent reference area to compare vegetative growth and establishment to the disturbance area. Vegetation seen here predominantly sand dropseed, sideoats and blue grama, western wheatgrass, etc...