

# Inspection Photos

API: 05-067-08228

Operator: XTO ENERGY INC.

Inspection Number: 680602429

Inspection Date: 1/9/2018



**Photo 1. View of the project area from the northwestern corner facing center.**



**Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.**



**Photo 3. View of the western portion of the project area from northwestern corner facing southward. Revegetation is progressing, with grasses such as crested wheatgrass (*Agropyron cristatum*), smooth brome (*Bromus inermis*) and western wheatgrass (*Pascopyrum smithii*) as well as sagebrush (*Artemisia tridentata*).**



**Photo 4. View of area in the northwestern portion of the interim reclamation area where concentrated stormwater is starting to erode the interim reclamation area.**



**Photo 5. View cobble run-down in the southern portion of the project area. This is filling with sediment and soon require maintenance.**



**Photo 6. View of cobble check dam and diversion in the southeastern portion of the project area. This is full of sediment and needs maintenance.**



**Photo 7. View of diversion in the eastern portion of the project area facing northward. Diversion is full of sediment and needs maintenance.**



**Photo 8. View of roadside drainage full of sediment that needs maintenance.**