



Inspection Photos
Location Name: Extraction Windsor LV2
Location # 449441



AWI Enclosed ECD in operation on location sound walls on west side removed



AWI Enclosed ECD