

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2018

Submitted Date:

01/18/2018

Document Number:

674200421**FIELD INSPECTION FORM**Loc ID 335592 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	
Adamczyk, Megan		megan.adamczyk@state.co.u s	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280540	WELL	PR	07/01/2017	GW	123-23288	COAL CREEK 31-19	PR

**General Comment:**

**Inspected Facilities**

Facility ID: 280540 Type: WELL API Number: 123-23288 Status: PR Insp. Status: PR

**Complaint**

Comment: Complaint #: 200445337

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 1-18-2018 Time 1130 Hrs

Contacted by Inspector:

Date: 1-18-2018 Time 1330 Hrs

Well Number#: Location #: 335592

Inspection Document #: 674200421

Nature of complaint: Noise

Field Inspector Actions:

On 1-18-2018, I was contacted by James Precup NE supervisor of the COGCC in reference to a complaint of noise coming from a location near the residence of the complainant in Erie.

On 1-18-2018 I contacted the complainant who indicated she was experiencing noise coming from the location west of her residence in Windsor. She indicated the noise was coming from the Crestone Peak resources plugging site at Coal Creek location at approx. 2000hrs to 2130hrs on 1-17-2018.

I conducted inspection of the Crestone Peak Coal Creek location and I observed a plugging operation on location. At the time of the inspection I observed normal plugging operations occurring on location. I spoke with the operator and asked what time operations shut down on 1-17-2018 and he indicated they shut down and were off location at approx. 1830hrs on 1-17-2018.

All information reviewed and site inspection information were submitted to the COGCC for further review.

I did not observe any violations of COGCC rules at the time of the inspection.

Corrective Action:

Date:

**Cement**Cement Contractor

Contractor Name: \_\_\_\_\_

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

<u>Comment:</u>	RIH w/WL check plug depth set CIBP dump 2 sxs at approx 700'	Date:
Corrective Action:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT