

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/18/2018

Submitted Date:

01/19/2018

Document Number:

679700797

FIELD INSPECTION FORM

Loc ID 435380 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Regulatory, Foundation		regulatory@foundationenergy.com	Regulatory Email
MacLaren, Joe		joe.maclaren@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435380	LOCATION	AC			-	WICKSTROM 6 CTB	EI
453779	SPILL OR RELEASE	AC			-	Wickstrom Central Tank Battery	EI

General Comment:

[COGCC Environmental Inspection - spill ID#453779 at heater treater. No other onsite facilities were inspected and any corrective actions required by inspection #678800393 remain in effect.](#)

Inspected Facilities

Facility ID: 435380 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 453779 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: COGCC inspection of spill from heater treater, occurred on 1/17/2018, reported on 1/18/2018. Gasket failure on heater treater. Operator is replacing upper and lower gaskets and both pressure release valves. Replaced PRVs to be tested. No free liquids observed. Operator plans to scrap most heavily impacted surface soil for disposal. Confirmation soil samples will be collected from impacted are to confirm compliance with Table 910-1. COAs will be applied to Supplemental Spill Report to submit Root Cause/Corrective Actions for overpressure and/or gasket failure.

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700798	Wickstrom 6 CTB Photos 01/18/2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4355235