

Inspection Photos

API: 05-067-06545

Operator: HOLCOMB OIL & GAS INC

Inspection Number: 680602431

Inspection Date: 1/9/2018



Photo 1. View of the northeastern portion of the project area (cut-slope). Straw blanket for erosion control is no longer functioning. Netting debris needs to be removed and erosion stabilized.



Photo 2. Another view of the northeastern portion of the project area. Wattles are full of sediment and need maintenance. Run-on controls appear needed.



Photo 3. View of Scotch thistle (*Onopordum acanthium*) growing on the well pad.



Photo 4. View of Scotch thistles within the southern portion of the interim reclamation area.



Photo 5. View of the southeastern portion of the project area from the southern corner facing northeastward.



Photo 6. View of the project area from the southern corner facing center.