

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2018

Submitted Date:

01/19/2018

Document Number:

689400871**FIELD INSPECTION FORM**
 Loc ID 324492 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Roy, Catherine		catherine.roy@state.co.us	
All Inspections,		inspection@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300502	WELL	PR	07/21/2015	GW	051-06086	FEDERAL 11-89-17 1	PR

General Comment:

This is a follow up inspection to FIR Doc#680200094 and 680602161. Any corrective actions not addressed from previous inspections are still applicable.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced water signs have been updated.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Posted Emergency Contact Number 1-866-261-9766
Corrective Action:	Date:

Good Housekeeping:			
Type	TRASH		
Comment:	Trash mentioned on previous inspections has been removed. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	300502	Type:	WELL	API Number:	051-06086	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Could not do complete stormwater inspection due to snow cover. Could not evaluate stormwater erosion at the well pad entrance where road-side stormwater flows onto the well pad. Original corrective action date is still applicable until site can be reevaluated when conditions allow.</p> <p>Corrective Action: Install and maintain stormwater controls to stabilize erosion at the entrance to the well pad</p> <p>Date: 12/02/2017</p>						
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689400872	Federal 11-89-17 1 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4356194