

Interim Reclamation and Stormwater Inspection

January 12, 2018

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 441121

Inspection Document #: 682403215

Weld County, CO

SESE Section 32 T5N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: State Pronghorn /44-32 Pad

Location ID: 441121



Photo 1. Photo taken from the eastern location , facing South. Photo indicates unmanaged Russian thistle (*Salsola tragus*-tumbleweed) throughout the perimeter and interim areas which is considered weed debris.



Photo 2. Photo taken from the eastern location, facing East. Unconsolidated soil material along the eastern fill slope. Operator needs to stabilize all unconsolidated soil material.

Inspection Photos
Location Name: State Pronghorn /44-32 Pad
Location ID: 441121



Photo 3. Photo taken from the eastern location, facing East. Sediment trap in need of maintenance. See comments under Photo 1.



Photo 4. Photo taken from the southern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: State Pronghorn /44-32 Pad
Location ID: 441121



Photo 5. Photo taken from the southwestern location, facing North. See comments under Photo 1.



Photo 6. Photo taken from the northwestern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: State Pronghorn /44-32 Pad
Location ID: 441121



Photo 7. Photo taken from the southern perimeter of location, facing West. Interim areas are not reflective of reference area vegetative levels.



Photo 8. Photo taken from the southern location, facing West. See comments under Photo 1.

Inspection Photos

Location Name: State Pronghorn /44-32 Pad

Location ID: 441121



Photo 9. Photo taken from the northern location, facing East. See comments under Photo 1.