

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2018

Submitted Date:

01/23/2018

Document Number:

677400407**FIELD INSPECTION FORM**Loc ID 305923 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|-----------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | ALL INSPECTIONS |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 283736 | WELL | SI | 02/01/2017 | OW | 123-23685 | HARSH 1-31 | SI |

General Comment:

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | ok | | |
| Corrective Action: | | | Date: _____ |

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|------------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | intermitter controller on wellhead | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-------------------|-------|--|
| Flaring: | | | |
| Type | Ignitor/Combustor | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 283736 Type: WELL API Number: 123-23685 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: whole lease SI

Corrective Action: _____ Date: _____

BradenHeadComment: ok

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|-----------------------------|----------|------------|
| <u>high risk inspection</u> | montoyaj | 01/23/2018 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------------|---|
| 677400408 | Battery Prod Equipment and wellhead | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4359243 |