

Inspection Photos

API: 05-067-07674

Operator: XTO ENERGY INC

Inspection Number: 680602433

Inspection Date: 1/9/2018



Photo 1. View of project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Approximately 100 Scotch thistles are present within the interim reclamation areas.



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 4. View of barbed wire within the southern portion of the project area.



Photo 5. View of the northern portion of the project area from the northwestern portion of the project area facing eastward.