

Inspection Photos

API: 05-067-08149

Operator: XTO ENERGY INC

Inspection Number: 680602441

Inspection Date: 1/9/2018



Photo 1. View of project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*) and smooth brome (*Bromus inermis*).



Photo 3. View of the northern portion of the project area from the northeastern corner facing westward.