

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/16/2018

Submitted Date:

01/17/2018

Document Number:

688600219**FIELD INSPECTION FORM**

Loc ID 428669 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 1Name of Operator: UNKNOWN

Address: _____

City: _____ State: _____ Zip: _____

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|---------------------------|---------|
| Andrews, Dave | | david.andrews@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 425793 | WELL | TA | 10/12/2011 | LO | 077-40017 | Lloyd and Lowell 1 | TA |

General Comment:

Orphan well plugging project. Contractor is RACS.

Inspected FacilitiesFacility ID: 425793 Type: WELL API Number: 077-40017 Status: TA Insp. Status: TA**Workover**

Comment: 8 am on location. Slickline tagged at 142', about the depth of the casing leak indicated on caliper log.
Well static, gas not detected with 4 gas meter.
RIH tubing to 139' and circulated.
Pumped 40 sacks cement. Well static.
Off location 11:30.

Corrective Action: **Plug and abandon.**

Date: 01/31/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401517614 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4353800 |