

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2018

Submitted Date:

01/24/2018

Document Number:

680602444

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
326137 \_\_\_\_\_ ROY, CATHERINE \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
 Name of Operator: XTO ENERGY INC  
 Address: 600 E EXCHANGE AVE  
 City: FORTH WORTH State: TX Zip: 76164

**Findings:**

6 Number of Comments  
 0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	All Inspections
Hixon, Logan	(505) 386-8018	logan_hixon@xtoenergy.com	
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215932	WELL	PR	08/01/1991	GW	067-07537	HUBER-JEFFRIES 1-5	RI

**General Comment:**

This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.

**Inspected Facilities**

Facility ID: 215932 Type: WELL API Number: 067-07537 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by irrigated grass field and farming structures/development. Revegetation is progressing within the interim reclamation areas.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment What appears to be surface owner trailers and equipment are stored southwest of the working area. It appears to be within the outer edge of the project area. If surface owner storage expands toward project area it will need removal.

Corrective Action

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_



**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680602445	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4359775">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4359775</a>