

Inspection Photos

API: 05-067-07554

Operator: XTO ENERGY INC

Inspection Number: 680602446

Inspection Date: 1/9/2018



Photo 1. View of project area from the eastern corner facing center.



Photo 2. View of the eastern portion of the project area from the eastern corner facing northward.



Photo 3. View of the southern portion of the project area from the eastern corner facing southwestward. Revegetation is sparse in areas but progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*).



Photo 4. View of scouring and erosion occurring within the southern portion of the project area.



Photo 5. View of erosional channels in the southern portion of the project area.



Photo 6. View of what appears to be surface owner vehicle and trailer in the western portion of the project area.