

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401525582

Date Received:

01/25/2018

Spill report taken by:

LUJAN, CARLOS

Spill/Release Point ID:

443844

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: CAERUS PICEANCE LLC	Operator No: 10456	<b>Phone Numbers</b>
Address: 1001 17TH STREET #1600		Phone: (970) 2852739
City: DENVER State: CO Zip: 80202		Mobile: (970) 9874650
Contact Person: Brett Middleton		Email: bmiddleton@caerusoila.ndgas.com

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400928465

Initial Report Date: 10/31/2015 Date of Discovery: 10/30/2015 Spill Type: Recent Spill

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR NESW SEC 36 TWP 7S RNG 96W MERIDIAN 6

Latitude: 39.390552 Longitude: -108.061925

Municipality (if within municipal boundaries): County: GARFIELD

#### Reference Location:

Facility Type: WATER GATHERING SYSTEM/LINE ☐ Facility/Location ID No

☒ No Existing Facility or Location ID No.

☐ Well API No. (Only if the reference facility is well) 05- -

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=100

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: TBD.

#### Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: partly cloudy, fair

Surface Owner: FEE Other(Specify): Encana

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☒ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☒

As defined in COGCC 100-Series Rules

A 1" ball valve in the High Mesa to Wallace Creek 12" Water pipeline vault was found half open, resulting in release of produced water to surrounding area on slope, approximately 300 yards above Pete and Bill Creek. Immediate measures were taken to isolate line, stop flow and prevent surface flow of release from reaching the creek. Produced water was drawn out of the vault and remaining static volume in line was removed at injection facility, C17OU. No surface flow of the release reached the creek. Sampling of soils in affected area is being done.

## OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
10/30/2015	NRC	Antony Greer	800-424-8802	report # 1132158
10/30/2015	COGCC	Carlos Lujan	970-286-3292	left voice mail

#1	Supplemental Report Date:	01/04/2018
Cause of Spill (Check all that apply) <input checked="" type="checkbox"/> Human Error <input type="checkbox"/> Equipment Failure <input type="checkbox"/> Historical-Unknown <input type="checkbox"/> Other (specify) _____		
Describe Incident & Root Cause (include specific equipment and point of failure) <div style="border: 1px solid black; padding: 10px; min-height: 100px; margin-top: 5px;">           A valve was found in the open position allowing fluid to be released.         </div>		
Describe measures taken to prevent the problem(s) from reoccurring: <div style="border: 1px solid black; padding: 10px; min-height: 100px; margin-top: 5px;">           A plug was put in the valve that was found open and soil has been remediated to meet table 910-1 please see document # 401502925         </div>		
Volume of Soil Excavated (cubic yards): _____		
Disposition of Excavated Soil (attach documentation) <input type="checkbox"/> Offsite Disposal <input checked="" type="checkbox"/> Onsite Treatment <input type="checkbox"/> Other (specify) _____		
Volume of Impacted Ground Water Removed (bbls): _____		
Volume of Impacted Surface Water Removed (bbls): _____		

## Form 27 Remediation Project No:

Signed: \_\_\_\_\_ Print Name: Brett Middleton

Title: Sr. Env. Specialist Date: 01/25/2018 Email: bmiddleton@caerusoilandgas.com

<u>COA Type</u>	<u>Description</u>

**Attachment Check List**

**Att Doc Num**      **Name**

--	--

Total Attach: 0 Files

**General Comments**

**User Group**      **Comment**      **Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)