

Inspection Photos

API: 05-067-08150

Operator: XTO ENERGY INC

Inspection Number: 680602448

Inspection Date: 1/9/2018



Photo 1. View of the western portion of the project area from the southwestern edge facing northward. Berms are seeded and revegetating.



Photo 2. View of the northeastern portion of the project area from the northeastern corner facing southeastward.



Photo 3. View of the northern portion of the project area from the northern edge facing westward.



Photo 4. View of green netting debris on cut-slope that needs to be removed and properly disposed of.



Photo 5. View of erosion occurring at the well pad entrance facing southward.