

Inspection Photos
Location Name: Dyer – USX A #3-17
API: 05-123-24592



Photo 1: Location, looking SW



Photo 2: Wellhead, looking N

Inspection Photos
Location Name: Dyer – USX A #3-17
API: 05-123-24592



Photo 3: Unused pipe at separator



Photo 4: Weeds in tank battery, berm

Inspection Photos
Location Name: Dyer – USX A #3-17
API: 05-123-24592



Photo 5: Marked, tagged risers W of separators