

Inspection Photos
Location Name: Rouse USX A #5-17
API: 05-123-24696



Photo 1: Wellhead, looking SE. Arrow emphasis from inspector is on damaged sign

