

Final Reclamation Inspection

January 9, 2018

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 327445

Inspection Document #: 682403235

Weld County, CO

NESW Section 7 T7N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ROTH #11-7R
Location ID: 327445



Google Earth aerial imagery taken October 9, 1989 illustrating no access roads were pre-existing prior to oil and gas operations.

Inspection Photos
Location Name: ROTH #11-7R
Location ID: 327445



Aerial imagery from COGCC GISOnline database taken in 2015 illustrating the well location and battery location during operations. This is the most recent aerial imagery.

Inspection Photos
Location Name: ROTH #11-7R
Location ID: 327445



Photo 1. Photo taken from the pit at the battery location, facing North. Operator has failed to backfill pit per Rule 1004.a.




Photo 2. Photo taken from the battery location, facing South. Operator has failed to remove equipment within 3-months of plugging the well, including the meter shed, tank, pig station, and riser.

Inspection Photos
Location Name: ROTH #11-7R
Location ID: 327445



Photo 3. Photo taken from the battery location, facing Northwest. See comments under Photo 2.



Photo 4. Photo taken from the access road to the battery location, facing West. Operator has failed to perform reclamation activities within 3-months of plugging the well on cropland.

Inspection Photos
Location Name: ROTH #11-7R
Location ID: 327445



Photo 5. Photo taken from the eastern battery location, facing West. See comments under Photo 4.



Photo 6. Photo taken from the access road to the well location, facing East. See comments under Photo 4.

Inspection Photos
Location Name: ROTH #11-7R
Location ID: 327445



Photo 7. Photo taken from the well location, facing East. See comments under Photo 4.



Photo 8. Photo taken between the well location and battery location, facing South. Operator has failed to remove equipment within 3-months of plugging the well.