

Inspection Photos

API: 05-067-09194

Operator: Maralex Disposal LLC

Inspection Number: 680602448

Inspection Date: 1/17/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 3. View of the northern portion of the project area from the southwestern edge facing eastward.



Photo 4. View of area in the northeastern corner of the well pad where stormwater flows run-onto the well pad and are eroding the cut-slope. Diversion ditches are full of sediment.



Photo 5. View of sediment deposition and erosional channeling in the northeastern portion of the project area.



Photo 6. Another view of erosional channeling and diversion full of sediment in the northeastern corner of the project area.