


Location Name: Sandy Hill Land Application Site: Facility ID 448950 Inspection Date: 01/25/2016



Aerial Image from Google Earth showing Land Application area, soil sample locations, and photograph locations.  
Aerial Image Date = 06/14/2016.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Sandy Hill Land Application Site**  
**Facility ID: 448950**  
**Inspection Date: 01/25/2018**



**Photo 1 – Photo of soil sample location SS-1, looking north.**  
**Soil Sample SS-1 location Lat/Lon = 40.37533 / -104.23270**



**Photo 2 – Photo of dried drilling fluid at soil sample location SS-1.**



## Inspection Photos

Location Name: Sandy Hill Land Application Site

Facility ID: 448950

Inspection Date: 01/25/2018



**Photo 3 – Photo of soil sample location SS-1.**



**Photo 4 – Photo from northwest corner of Winick property looking east down property line. Sandy Hill Land Application area is north of property. Area of Winick property beneath snowdrift has been impacted by the migration of drilling fluid.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Sandy Hill Land Application Site**  
**Facility ID: 448950**  
**Inspection Date: 01/25/2018**



**Photo 5 – Photo from southwest corner of Sandy Hill Land Application area looking east down property line. Winick property is on southside of fence line in the right of the picture.**



**Photo 6 – Photo from southwest corner of Sand Hill Land Application area looking north down western property line.**





## Inspection Photos

Location Name: Sandy Hill Land Application Site

Facility ID: 448950

Inspection Date: 01/25/2018



**Photo 7 – Photo from rise on Sandy Hill Land Application area looking west toward southwest corner of land application area.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Sandy Hill Land Application Site**  
**Facility ID: 448950**  
**Inspection Date: 01/25/2018**



**Photo 8 – One of two areas of staged drill cuttings, looking north.**



**Photo 9 – One of two areas of staged drill cuttings, looking west.**



## Inspection Photos

Location Name: Sandy Hill Land Application Site

Facility ID: 448950

Inspection Date: 01/25/2018



**Photo 10 – Photo of ponded drilling fluid on land application site, taken from Lat/Lon 40.37827,-104.23025 looking west-northwest.**



**Photo 11 – Photo of drilling fluids pond looking southeast.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Sandy Hill Land Application Site

Facility ID: 448950

Inspection Date: 01/25/2018



**Photo 12 – Photo of area where drilling fluids are drained to flow into pond.**



**Photo 13 – Photo near edge of pond where drilling fluids are dumped.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Sandy Hill Land Application Site**  
**Facility ID: 448950**  
**Inspection Date: 01/25/2018**



**Photo 14 – Drilling fluids and stormwater mixing with waste runoff in northwest corner of Sandy Hill Land Application area. Gate accesses State Land Board land to the west.**



**Photo 15 – Drilling fluids and stormwater mixed with waste runoff into ditch at northwest corner of Sandy Hill Land Application area, looking south. State Land Board land is across the fence to the west.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Sandy Hill Land Application Site

Facility ID: 448950

Inspection Date: 01/25/2018



**Photo 16 – Photo looking west across fence at dried drilling mud of spill onto State Land Board land. Spill was reported by Operator and assigned Spill ID #452946.**



**Photo 17 - Photo looking northwest across fence at dried drilling mud of spill onto State Land Board land. Spill was reported by Operator and assigned Spill ID #452946.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Sandy Hill Land Application Site**  
**Facility ID: 448950**  
**Inspection Date: 01/25/2018**



**Photo 18 – Looking south on Sandy Hill Land Application western boundary where spill onto State Land Board land occurred.**



**Photo 19 - Looking north on Sandy Hill Land Application western boundary where spill onto State Land Board land occurred.**

