

Inspection Photos

API: 05-067-08089

Operator: WPX

Inspection Number: 680602456

Inspection Date: 1/17/2018



Photo 1. View of the project area from the northeastern edge facing center. Project area is not reclaimed.



Photo 2. View of the northern portion of the project area from the northeastern edge facing westward.



Photo 3. View of the eastern portion of the project area from the access road facing southward.



Photo 4. View of erosional pedestaling and channeling (approximately 1.5 feet wide and deep) within the access road.



Photo 5. View of soil stockpile approximately 15 feet high in the southeastern portion of the project area.



Photo 6. View of erosional channeling in the southern portion of the project area.



Photo 7. View of fill slope in the southwestern portion of the project area.



Photo 8. View of flat well pad from the northwestern corner facing center.



Photo 9. View of erosional channels forming within the northern cut-slope.



Photo 10. Another view erosional channeling within the northern portion of the project area. Soils have eroded to bedrock in areas.



Photo 11. View of wood debris stockpiled along the eastern edge of the project area.