

Inspection Photos

API: 05-067-08485

Operator: HILCORP ENERGY COMPANY

Inspection Number: 680602458

Inspection Date: 1/17/2018



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern edge facing westward. Culvert needs to be removed.



Photo 3. View of the northeastern portion of the project area from northern corner facing southward.



Photo 4. View sediment piles in the eastern portion of the project area. Sediment needs to be contained to prevent run-off and run-on.



Photo 5. View of musk thistles (*Carduus nutans*) in the northern portion of the project area. Approximately 200 individuals identified on location.



Photo 6. View of anchor cable in the southern portion of the project area.