

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/25/2018

Submitted Date:

01/29/2018

Document Number:

690100337

FIELD INSPECTION FORM

Loc ID 311306 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444850	TANK BATTERY	AC	02/16/2016		-	NEFF 1 AND 2 BATTERY	EG

General Comment:

Details of observations made during this field inspection are available in the flowline section of this report. Photos uploaded can be accessed via link(s) at end of report.

Inspected Facilities

Facility ID: 444850 Type: TANK API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type: Process Piping	1 of Lines
----	----------------------	------------

Flowline Description

Flowline Type: Process Piping Size: 2" Material: Poly
 Variance: Age: New Contents: Produced Water

Integrity Summary

Failures: Spills: No Repairs Made:
 Coatings: H2S: No Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: COGCC Inspector met with KPK Supervisor Jeff Peterson on location. Field/ construction work was in process at the Neff Battery. Excavation work observed in progress; flowline upgrades/ process pipe was being installed at the produced water tank using 2" HDPE with tracer wire. No actions required were identified at the time of this field inspection.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100344	Signage and battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363103
690100345	HDPE pipe/ tracer wire installation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4363104