

# Inspection Photos

API: 05-067-06443

Operator: WPX ENERGY PRODUCTION LLC

Inspection Number: 680602460

Inspection Date: 1/17/2018



**Photo 1. View of the project area from the southeastern corner facing center.**



**Photo 2. View of the eastern portion of the project area from the southeastern edge facing northward.**



**Photo 3. View of the southern portion of the project area from northern corner facing westward. Stormwater controls with cobble run-downs in this portion of the project area appear to be functioning.**



**Photo 4. View of diversion channel, approximately 3.5 feet wide and deep, in the northeastern portion of the project area (facing upstream) that is eroding and needs stormwater controls.**



**Photo 5. Downstream view of diversion channel draining from the northeastern portion of the project area. Stormwater controls need to be installed to de-energize flows coming off of the well pad.**



**Photo 6. View of diversion channel in northern project area (upstream from photos 5 and 6) that is full of sediment and needs maintenance.**