

Inspection Photos

01/29/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -
96340

Location ID: 443191

Inspection Doc. Number: 682503108
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 443191



Photo 1: Photo taken from the northwest corner of the location, facing east. Photo shows overview of the location.



Photo 2: Photo taken from the northwest corner of the location, facing southeast. Photo shows overview of the location.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 443191



Photo 3: Photo taken from the northwest corner of the location, facing south. Photo shows overview of the location.



Photo 4: Photo taken from the north end of the location, facing south. Photo shows the vegetation over the reclamation area. Photo shows vegetation appears to be a monoculture of undesirable weedy plant species such as kochia and Russian thistle.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 443191



Photo 5: Photo taken from the southeast corner of the location, facing west. Photo shows vegetation over the reclamation areas appears to be progressing along the perimeter edges of the location, however, the large majority of the location is predominantly undesirable weedy plant species.



Photo 6: Photo taken from the southeast corner of the location, facing northwest. Photo shows vegetation over the reclamation areas appears to be progressing along the perimeter edges of the location, however, the large majority of the location is predominantly undesirable weedy plant species.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 443191



Photo 7: Photo taken from the southeast corner of the location, facing north. Photo shows vegetation over the reclamation areas appears to be progressing along the perimeter edges of the location, however, the large majority of the location is predominantly undesirable weedy plant species.



Photo 8: Photo taken from the south end of the location, facing north. Photo shows the vegetation over the reclamation area. Photo shows vegetation appears to be a monoculture of undesirable weedy plant species such as kochia and Russian thistle.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 443191



Photo 9: Photo taken from the central area of the location. Photo shows vegetation over the reclamation area is predominantly undesirable weedy plant species.



Photo 10: Photo taken from the northwest corner of the location, facing west. Photo shows access road reclamation appears to be progressing.



Photo 11: Photo taken from the adjacent reference area. Photo shows vegetation over the reference area. Vegetation seen in photo predominantly Blue grama, Buffalo grass, threeawn, sand dropseed, western wheatgrass and yucca.