

# Inspection Photos

API: 05-067-08201

Operator: Hilcorp Energy Company

Inspection Number: 680602462

Inspection Date: 1/17/2018



**Photo 1. View of the project area from the northwestern corner facing center.**



**Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.**



**Photo 3. View of the western portion of the project area from northwestern corner facing southward. Erosion is occurring off of the northwestern edge of the well pad.**



**Photo 4. View of erosion occurring within the northern portion of the project area.**



**Photo 5. View of area in the eastern portion of the project area where significant quantities of sediment run onto the well pad. Anchor marker is largely buried.**



**Photo 6. View of erosion channels and Russian thistle (*Salsola tragus*) debris within the southern portion of the project area. This slope needs stabilization, and seeding. R. thistle needs to be removed and properly disposed of.**



**Photo 7. View of erosional channel approximately 3 feet wide and deep in the southern portion of the project area.**



**Photo 8. View of unmarked rig anchor in the southern portion of the project area.**



**Photo 9. View of erosional channels up to 3 feet wide and deep in the southern portion of the project area.**



**Photo 10. View of another erosional channel up to 3 feet deep in the southern portion of the project area.**