

February 02, 2018

Jamie Presgrove
21995 Co Rd 80
Eaton, CO 80615
(via email: j21995cp@gmail.com)

Dear Ms. Presgrove,

The Colorado Oil and Gas Conservation Commission (COGCC) received your complaints regarding noise/ vibrations you attributed to an oil and gas location in the vicinity of your residence. Your complaints are recorded in the following document numbers, which can be reviewed via the “Complaints” link, on our website (<http://cogcc.state.co.us/>):

- 200443964;
- 200444165;
- 200444246;
- 200444634;
- 200444674;
- 200444780; and
- 200444809.

The actions taken to address your complaints are summarized below.

- On 09/20/2017 a COGCC inspector conducted an inspection of the Burroughs South location, operated by Extraction Oil & Gas Inc. (extraction), documented in Field Inspection Report (FIR) #684904407. The inspector observed that the location was moving into production status and that a compressor had recently been blown down prior to bringing it online. No upset conditions or violations of COGCC rules were observed;
- On 09/20/2017 the inspector conducted an inspection of the SRC Gies Pad, operated by Bayswater Exploration and Production LLC (Bayswater), documented in FIR #684904409. The inspector determined that the pad was replacing a compressor unit with a new unit. A crane helped place the unit and work on pipes was completed at the time of the inspection. The location had been shut in since before the time of your complaint;
- On 09/20/2017 the inspector conducted an inspection of the Triangle 4-22 location, operated by Bayswater (documented in FIR #684904412). The



inspector determined that the location had been shut in at the time of your complaint and emission control devices had continued to run to deal with VOCs from production tanks. No violations of COGCC rules were observed ;

- On 12/15/2017 a COGCC inspector conducted an inspection of the SRC Gies Pad (documented in FIR #684904773). The inspector determined that the location was undergoing maintenance to replace a soundwall, including installing post holes for the new walls. No violations of COGCC rules were observed;
- On 01/08/2018 a COGCC inspector conducted an inspection of the Burroughs South location (documented in FIR #684904846). The inspection included a sound study which was correlated with the log of vibrations you provided. The survey indicated that the location noise levels exceeded the limits established in COGCC Rule 802. FIR #684904846 was issued to the operator with corrective action to comply with Rule 802 and obtain a low frequency impact analysis and identify control measures; and
- Extraction personnel provided notice to COGCC that a faulty ECD was identified as the source of the low frequency noise and was replaced, resolving the low frequency noise issue.

COGCC FIRs are available on the COGCC website by via the "Data" link, then selecting "Inspection/ Incident" search link, and entering the above referenced FIR number(s) into the "document number" search field.

COGCC staff did not identify any violations of COGCC rules that would lead to the issuance of a notice of alleged violation (NOAV) related to your complaints. Accordingly, the COGCC has closed your complaints.

If you have questions regarding these complaints, you may contact me.

Sincerely,

A handwritten signature in blue ink that reads "Megan J Adamczyk".

Megan Adamczyk, Complaint Specialist
Email: dnr_cogcc.complaints@state.co.us
Phone: 888-235-1101