

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2018

Submitted Date:

02/04/2018

Document Number:

680402484**FIELD INSPECTION FORM**Loc ID 322331 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES, INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Burger, Craig		craig.burger@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Reed, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111193	PIT	AC	09/23/1999		-	CALF CANYON 24-2	AC
210294	WELL	SI	04/27/2012	GW	045-06050	CALF CANYON-FEDERAL 24-2	PA

General Comment:Plug and abandon well.

Location

Lease Road:			
Type	Main		
comment:	Private		
Corrective Action	L	Date:	
Type	Access		
comment:	BLM		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign removed for wellwork.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	Hogwire & rebar.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 111193 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 210294 Type: WELL API Number: 045-06050 Status: SI Insp. Status: PA

CementCement ContractorContractor Name: A Plus Well Service

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 1300-984,227-127,62Cement Volume (sx): 121Good Return During Job: YESCement Type: BComment:

1/31/2018- Lobo rig #101. Rig up to pull tubing. 7 5/8" casing set @ 2751' w/ stage tool @ 1151'. CIBP set @ 1300'. Perfs 1122'-1136'

2/1/2018- Pull tubing. Run in tubing, tag bottom @ 1290'. Rig up cementing head. Pump 80 sks 15.5 lb/gal Class "B" cement.

2/2/2018 - RIH w/ tubing. Tag top of plug #1 @ 984'. Pull back to 227'. Pump 25 sks 15.5 lb/gal Class "B" cement. Pull back to 62'. Pump 15.5 lb/gal Class "B" cement to surface. Excavate and cut off wellhead 3' below surface level. Pump 15.5 lb/gal Class "B" cement to top off 10.75" and 7.625" casing annulus. Weld information plate to casing. Begin reclamation.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: 111193Lat: 39.532743Long: -108.707175Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: YESComment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680402485	Inspection photos 2/1-2/2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4369450