

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2018

Submitted Date:

02/03/2018

Document Number:

688301142**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 449376 Sherman, Susan 2A Doc Num: _____

Operator Information:OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: 600 N DAIRY ASHFORD RDCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	Regulatory Coordinator
Strickler, Robert		Robert.D.Strickler@conocophillips.com	All DJ Basin Inspections
ConocoPhillips		COPColoradoReg@conocophillips.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449378	WELL	DG	01/15/2018		001-10008	Aspen 3-65 15-14 2DH	DG

General Comment:

Inspector received at call from COP at 2:55 pm on 2/2/2018 reporting a spill on the drilling pad. Site inspection completed at ~5:30 pm on 2/2/2018.

Approximately 4 1/2 BBLs of drilling fluids/cuttings were spilled outside of containment when a hole was made in the tank while removing E&P waste. All spilled fluids except some under the tank was removed and hauled offsite for disposal. The remaining will be disposed offsite when the tank is moved. All equipment was being moved to the next location. The ground was scrapped with a loader until the ground was dry as seen in the attached photos. A Form 19 I is in process per operator. COGCC Field Inspector was contacted by operator immediately. Operator to contact landowner and Adams CTY LGD at completion of investigation.

LocationOverall Good: ☐**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	location sign at gate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 449378 Type: WELL API Number: 001-10008 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: Nabors B16 Pusher/Rig Manager: Richard Perez
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____

Multi-Well: _____ Disposal Location: _____

Comment: _____

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688301144	ConocoPhillips Aspen 3-65 15-14 2DH	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4369632