

- Tyner – Lunt (EPA) 1
- 05-067-06140



Photo 1: Wellhead sign. Previous inspection.

- Tyner – Lunt (EPA) 1
- 05-067-06140



Photo 2: Wellhead sign.

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 3: Erosion channel at E side of tank battery. Previous inspection.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 4: Repaired erosion channel on E side of tank battery.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 5: Erosion channels along S perimeter. Previous inspection.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 6: Repaired erosion channels along S perimeter.**



- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 7: Erosion channel on W side of tank battery. Previous inspection.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 8: Repaired erosion channel on W side of tank battery.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 9: Liner detached from wall. Previous inspection.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 10: Repaired liner.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 11: Tears in bottom of liner. Previous inspection.**

- Tyner – Lunt (EPA) 1
- 05-067-06140



**Photo 12: Replaced/repared liner.**