

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2018

Submitted Date:

02/05/2018

Document Number:

690100364**FIELD INSPECTION FORM**
 Loc ID 320426 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|----------------|-------------------------------|---------|
| Powell, Harold | (918)-774-3120 | hpowell@petrosharecorp.com | |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| Lloyd, Bill | | blloyd@petrosharecorp.com | |
| Brown, Devin | | dbrown@petrosharecorp.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 203732 | WELL | SI | 04/01/2017 | GW | 001-09292 | WYMAN 34-6 | EG |

General Comment:

[Photos uploaded can be accessed via link\(s\) at end of report.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|--|------------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | (2) unused unmarked flowline risers observed in the area of the horizontal separator; (1) 2" carbon steel riser near the inlet to the separator and (1) 2" carbon steel riser surrounded by fencing approximately 35' NW of the separator. | | |
| Corrective Action: | Comply with rule 603.f. For unused unmarked flowline risers 24hrs to lock out/ tag out; 30 days to remove unused risers. | | Date: 03/05/2018 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 203732 Type: WELL API Number: 001-09292 Status: SI Insp. Status: EG**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: COGCC Form 6 notice of intent to abandon doc #401400097 received on 01/05/2018.
 Wellhead valves are currently locked/ tagged out. No flowline available at wellhead.
 Disconnected equipment on location is considered unused equipment; COGCC rule 603.f. 90 days to remove unused equipment when machinery is required for removal.

Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 690100371 | Wellhead and signage | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4370549 |
| 690100372 | Unused flowline riser at horizontal separator | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4370550 |
| 690100373 | Unused unmarked flowline riser NW of separator | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4370551 |