

Well Name : Bullseye 2

API # : 067-09286



Photo 1: Wellhead sign.



Photo 2: Open top tank with below grade labels.

Well Name : Bullseye 2

API # : 067-09286



Photo 3: Tank labels below grade and not visible. NFPA label on fencing does not match label on tank.



Photo 4: Impacted soil around wellhead.

Well Name : Bullseye 2
API # : 067-09286



Photo 5: Impacted soil at rear of pump jack.



Photo 6: Mineral deposits on tank heater tube hatch.

Well Name : Bullseye 2

API # : 067-09286



Photo 7: Mineral ring around base of tank. Inside berms.



Photo 8: Algae in standing water.

Well Name : Bullseye 2

API # : 067-09286



Photo 9: Vehicle tracking on edge of disturbed area N side of pump jack.



Photo 10: Location overview.