

Inspection Photos
Location Name: Snooks A #2
API: 05-067-08870



Stained concrete pad and surrounding gravel around prime mover.



Absorbent granules on concrete pad.

Inspection Photos
Location Name: Snooks A #2
API: 05-067-08870



Secondary containment for lube oil container.



Absorbent rags on well head are saturated.

Inspection Photos
Location Name: Snooks A #2
API: 05-067-08870



Stained gravel at muffler exhaust.



Tie in for Le Platt B #2.

Inspection Photos
Location Name: Snooks A #2
API: 05-067-08870



Preparations for tie in.



Gathering line excavation. Le Platt B #2 in background.