

# Inspection Photos

02/05/2018

Operator: NIOBRARA ILLUMINATING GAS  
ASSOCIATES LLC - 63380

Location ID: 403658

Inspection Doc. Number: 682503114  
Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the well, facing north. Photo shows vegetation over the western portion of the location. Vegetation seen here is predominantly annual aster species.



**Photo 2:** Continued from photo 1: soils on location remains predominantly bare and exposed.



## Inspection Photos

Operator: NIOBRARA ILLUMINATING GAS ASSOCIATES LLC - 63380

Location ID: 403658



**Photo 3:** Photo taken from the north end of the location, facing east. Photo shows areas of the location and access road that remain unstabilized, and soils remain bare and exposed. Unable to find evidence that additional reclamation activities have been conducted.



**Photo 4:** Photo taken the east end of the location, facing south. Photo shows portions of the access road on location have not been reclaimed per reclamation rules. Erosion evident. Dark, stained/contaminated soils have not been removed.



Inspection Photos  
Operator: NIOBRARA ILLUMINATING GAS ASSOCIATES LLC - 63380  
Location ID: 403658



**Photo 5:** Photo taken from the east end of the location, facing south. Photo shows contaminants have not been removed. 6 foot measuring stick for reference.



**Photo 6:** Photo taken from the east end of the location. Photo shows contaminants have not been removed. 6 foot measuring stick for reference.



Inspection Photos  
Operator: NIOBRARA ILLUMINATING GAS ASSOCIATES LLC - 63380  
Location ID: 403658



**Photo 7:** Photo taken from the east end of the location, facing south. Photo shows contaminants have not been removed. 6 foot measuring stick for reference.



**Photo 8:** Photo taken from the east end of the location, facing north. Photo shows no additional reclamation activities have been conducted on location and access road.



## Inspection Photos

Operator: NIOBRARA ILLUMINATING GAS ASSOCIATES LLC - 63380

Location ID: 403658



**Photo 9:** Photo taken from the southeast end of the location, facing south. Photo shows pipe riser, fence and debris remains on the location. Equipment was identified as a "Gasline tie/well" in previous inspection.



**Photo 10:** Photo taken from the southeast end of the location. Photo shows gravel and debris remaining on location at the "Gasline tie/well".