

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo 1: Location, looking NW



Photo 2: Wellhead, looking S

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from prior inspection for comparison



Photo 3: Weeds removed

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from prior inspection for comparison



Photo 4: Pit 1 compromised by vegetation, damaged

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from prior inspection for comparison



Photo 5: Pit 3 compromised by vegetation

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from prior inspection for comparison



Photo 6: Weeds controlled at tank battery

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from prior inspection for comparison



Photo 7: Pit 2 liner, torn and compromised by vegetation

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo from R Allison's prior inspection for comparison purposes



Photo 8: Stained soil at transfer pump

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo 9: Pit 1, contents sagging into pit



Photo 10: Stained soil at exhaust

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo 11: Stained soil at ajax engine



Photo 12: Stained soil at loadout

Inspection Photos
Location Name: Dolan Ranches #13-27
API: 05-123-07364



Photo 13: Stained soil at base of tank at loadout



Photo 14: Stained soil and fluid at base of tank on NW side