

Inspection Photos
Location Name: Janet 0780 4-16H21
API: 05-057-06605



Photo 1. Overview of location taken on northwest side facing southeast..

Inspection Photos
Location Name: Janet 0780 4-16H21
API: 05-057-06605



Photo 2. Sagging silt fence as primary storm water control on south side of location.



Photo 3. Sagging silt fence acting as primary storm water control on east side of location.

Inspection Photos
Location Name: Janet 0780 4-16H21
API: 05-057-06605



Photo 4. Uncovered mud additives on location perimeter.



Photo 5. Uncovered mud additives on location perimeter.