

Inspection Photos

API: 05-067-09913

Operator: CATAMOUNT ENERGY PARTNERS LLC

Inspection Number: 680602470

Inspection Date: 1/17/2018



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the western portion of the project area from the northern corner facing southwestward.



Photo 3. View of the northeastern portion of the project area from northern corner facing southeastward.



Photo 4. View of an erosional channel approximately 5.5 feet wide and deep in the northern portion of the project area. Stabilization measures are needed here.



Photo 5. View of another erosional channel approximately 5 feet wide and deep in the eastern portion of the project area. Stabilization measures are needed here.



Photo 6. View of Russian knapweed (*Acroptilon repens*) infestation along the northeastern edge of the project area.