

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2018

Submitted Date:

02/13/2018

Document Number:

687900767

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
322257 _____ DURAN, JOHN _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Mehennett, Tom	(719) 275-3040/ (505) 330-1328	tbm3040@gmail.com	All Inspections
Sutphin, Dirk		dirk.sutphin@state.co.us	
Javernick, James	719-275- 3040/719-671- 3787	javernick1@gmail.com	All Inspections
Ash, Margaret		margaret.ash@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210076	WELL	PR	07/16/2002	OW	043-40012	ROBB-HIAWATHA 1	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:

Type	Capacity	#	Comment	Corrective Action	Date	corrective date
Ancillary equipment		# 1	Electrical box			
Pump Jack		# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLs	STEEL AST		
Comment:	1 - 210 bbl ST, The 15 ft tank now has 4 holes (2 on E. side and 2 on W. side) from a 30 caliber rifle.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 210076 Type: WELL API Number: 043-40012 Status: PR Insp. Status: PR

Producing Well

Comment: PR - Producing well that is Shut In, after shots pierced the East and West side of tank. Will Produce when holes have been fixed.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On site at 1:40pm. Met with Don Kear (pumper). He said he had been at wellsite on Friday (02/09/18) and everything seemed fine. When he came to the wellsite on Monday (2/12/18) he noticed the bullet holes and he contacted Jim Javernick and Jim Javernick contacted the Sherriff. There are 2 holes (entry) on the E. side of tank and 2 holes (exit) on the W. side of tank. There are also several dings on the W. side of tank. The tank is 15 ft tall and the holes are at about 12 ft, so the was no spill. The tank was emptied on Dec. 28,2017, so the current level is 58 inches. There closest structure is 1/4 mile to the East. The large white tank 1 mile to the North is the Florence water tank. Will revisit well site after holes in tank have been patched up. Off site at 2:00 pm	duranj	02/13/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687900768	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377319
687900769	Well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377320
687900770	2 holes, E. side, near seam and left of ladder	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377321
687900771	2 holes, E. side, near seam and above platform	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377322
687900772	E. side, seam above ladder platform	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377323
687900773	W. side, 2 holes	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377324
687900774	W. side tank South	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377325
687900775	W. side tank North	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377326
687900776	Pumpjack looking West	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377327