

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/09/2018

Submitted Date:

02/13/2018

Document Number:

689100117**FIELD INSPECTION FORM**

Loc ID 334104 Inspector Name: LUJAN, CARLOS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS Professional
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
334104	LOCATION	AC			-	RAMOS-68S96W 1NESW	EI

General Comment:

Site inspection conducted on February 09, 2018. Sunny and warm for this time of the year (about 55 oF). Site has four producing wells, two 300-bbl tanks for produced water and condensate storage and two separators. All equipment are properly fenced and labeled. The tanks are lined and have a steel wall secondary containment. No junk, staining, or trash was observed on site. The former pit (Closed) back filled and recountered shows no sign of subsidence.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 334104 Type: LOCATION API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689100118	Photo Report Ramos 1-23	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4377351