

Inspection Photos

Location Name: Lucero 34-10 flowline API: 05-123-17156 Spill ID #454029

Inspection Date: 02/14/2018



Photo 1 - Hammer union location of spill/release ID 454029



Photo 2 – Photo of flowline trench at release point, looking south.

Inspection Photos

Location Name: Lucero 34-10 flowline API: 05-123-17156 Spill ID #454029

Inspection Date: 02/14/2018



Photo 3 – Second hammer union suspected release point.



Photo 4 – with riser disconnected from wellhead.

