

Inspection Photos
Location Name: Law #1-17
Location ID: 319375



Photo 1: Location, looking NW, tank requires painting.

Photo 2: Wellhead, looking W

Inspection Photos
Location Name: Law #1-17
Location ID: 319375



Photo from J Rickard's prior inspection for comparison

Photo 3: Stained soil at wellhead, leaking at wellhead

Inspection Photos
Location Name: Law #1-17
Location ID: 319375



Photo from J Rickard's prior inspection for comparison



Photo 4: Unused compressor noted in prior inspection

Inspection Photos
Location Name: Law #1-17
Location ID: 319375



Photo from J Rickard's prior inspection for comparison



Photo 5: Emergency number decal not readable at 100 ft

Inspection Photos
Location Name: Law #1-17
Location ID: 319375



Photo from J Rickard's prior inspection for comparison



Photo 6: Unused equipment removed, some debris remains. Burrows in berms.

Inspection Photos
Location Name: Law #1-17
Location ID: 319375



Photo 7: Unused fence at wellhead

Photo 8: Stained soil at tank valve.