

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/16/2018

Submitted Date:

02/16/2018

Document Number:

684905049**FIELD INSPECTION FORM**Loc ID 319375 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments9 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243352	WELL	SI	06/01/2017	OW	123-11143	LAW 1-17	SI

General Comment:[CA dates used from doc#674103445, where applicable.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tanks are placarded		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact number not posted at wellhead or battery, as noted in prior inspection. Decal on production tank is not legible at 100 ft.

Corrective Action: Install sign to comply with rule 210.b

Date: 07/13/2016

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds at wellhead location		
Corrective Action:	Comply with rule 603.f	Date:	02/26/2018
Type	DEBRIS		
Comment:	Debris around tank battery		
Corrective Action:	Comply with rule 603.f	Date:	03/16/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused fence at wellhead		
Corrective Action:	Comply with rule 603.f	Date:	03/16/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused compressor at wellhead, as noted in prior inspection (no CA date given at time)		
Corrective Action:	Comply with rule 603.f	Date:	03/16/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Stained soil at wellhead, fluids on wellhead		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e. ; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 08/13/2016

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.569600,-104.802290
Comment:	Paint is chipped in places, rust at base of tank. Stained soil at valve on tank.				
Corrective Action:	Repair and paint tanks per Rule 804. (6 mo CA) Properly treat or dispose of oily waste in accordance with Rule 907.e. ; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (30 days CA)				Date: 03/16/2018

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Burrows in berms			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 03/16/2018

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.569600,-104.802290
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	120bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:	Shared with crude oil				
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 243352 Type: WELL API Number: 123-11143 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: SI. Last reported Aug 2017. Last reported production May 2017.No gas production reported.Corrective Action: Submit reports per Rule 206.Measure gas per Rule 329.Date: 03/16/2018**BradenHead**Comment: Bradenhead plumbed to surface.

Corrective Action:

Date: _____

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Contacted operator 02/16/18 at 1400hr about wellhead leak	pesickac	02/16/2018
Engineer D Burn included on inspection due to lack of gas reporting and prior engagement with site.	pesickac	02/16/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684905050	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4380963